			SECRI	ET		
	_				25	25X1 5X1
					0 -18-200518-08	
Tnis	document co	ontains			Copy 8 of 9 copie	es
3	pages.				29 February 1968	

## EVALUATION SUMMARY

Mission BX-6851

1. Processing and Titling - Field

2. Physical Condition - Good

3. Hypo Retention Rewashing required (Patch 3, HT-2 test)

4. Exposure (based on density) - Medium

- 5. General Comments:
  - A. Total mission contained 14 parts.
  - B. Part 8 required dual printing.
  - C. Dye retention was prevalent throughout the mission. It was reprocessed to remove excess dye.
  - D. Estimated cloud cover and/or water is 75%. 7 parts were 100% clouds and/or water.
  - E. Small emulsion skip type defect on Part 13, Frames 971-974. (Pictures recorded)
  - F. A few frames show evidence of erratic film tracking (camera); example: Part 9, Frames 609-628, Part 14, Frames 1038-1040.
  - G. Part 6, Frame 397 contained an ultrasonic splice. The splice apparently was not taped (reinforced) at presplice.
  - H. A few frames contain the clock in the format.
  - I. A small amount of pinholes was observed intermittently throughout the mission.
  - J. The first and last frames of most parts show evidence of handling marks. These are attributed to inserting grids and replacing idents in house.

S	E	$\mathbb{C}$	$\mathbb{R}$	E	T

## MISSION NO. BX-6851 EVALUATION REPORT

Evaluated By	Q.C. Technicians	Camera	Fwd/Aft
Evaluation Da	ate 22 February 1968	Emulsion_	3404

Film Metering

Normal for system

Film Tracking

Good

Clock Exposure

Good

Counter Operation

Operational

Data Chamber (image quality)

Good

Apparent Resolution

Normal

Apparent Granularity

Normal

Density

Medium to slightly heavy

Contrast

Normal

## Discrepancies:

<u>Part</u>	Frames	Comments
1	1-76 2-12	Intermittent edge wrinkle Fog
2		
3		
4		
5 .	378 380	HT-2 test spot Cinch mark
6	405 406	Cinch mark Ultrasonic splice
7	457 <b>-</b> 532	Emulsion scratch
8	533 <b>-</b> 608	Intermittent emulsion scratch
9		
10	685 <b>-</b> 752 685,688 686 748 741 <b>-</b> 751	Intermittent emulsion scratch Embedded dirt, abrasions, splice Abrasions HT-2 test spot Fog

Page 2

SECRET

## Discrepancies (Cont'd) Camera

<u>Part</u>	Frames	<u>Comments</u>
10	685-760	Intermittent emulsion scratch
11	761-836	Emulsion scratch
12	837 <b>-</b> 912	Intermittent emulsion scratch
13	913-988 971-974	Emulsion scratch Emulsion defect
14	989 <b>-</b> 1046 990	Emulsion scratch HT-2 test spot

Page 3

SFCRET